

STATE OF MAPYLAND

DEPARTMENT OF HEALTH AND MENTAL HYGIENE OFFICE OF ENVIRONMENTAL PROGRAMS P.O. BOX 13387

DATE

201 W. PRESTON STREET BALTIMORE, MARYLAND 21203

(301) 383-6650

SITE COMPLAINT

			NUMBER	DATE
		SC-0-	87-034	07/18/86
1.	Name of violator: BALTIMORE POST OFFICE Address: GO WAST OLIVER STREET MODIFICATION Phone: 301-2 Violation Type (with reference to Maryland Code) Water Pollution Control and Abatement (Health Environmental Article, Sections of the Control and Abatement (Health Environmental Article, Sections of the Control and Abatement (Health Environmental Article, Sections of the Control and Abatement (Health Environmental Article, Sections of the Control and Abatement (Health Environmental Article, Sections of the Control and Abatement (Health Environmental Article, Sections of the Control and Abatement (Health Environmental Article, Sections of the Control and Abatement (Health Environmental Article, Sections of the Control and Abatement (Health Environmental Article, Sections of the Control and Abatement (Health Environmental Article, Sections of the Control and Abatement (Health Environmental Article, Sections of the Control and Abatement (Health Environmental Article, Sections of the Control and Abatement (Health Environmental Article, Sections of the Control and Abatement (Health Environmental Article, Sections of the Control and Abatement (Health Environmental Article, Sections of the Control and Abatemental Article)	635	· <i>893</i> 3	
3.	Controlled Hazardous Substances (Health Environmental Article, Sections 7-201 to Landfills and Sludge Disposal (Health Environmental Article, Section 9-210) Other			L gave 51.05.02
4.	The existence of the above-mentioned violation(s) may subject you to prosecution a that the following corrective actions are necessary to remedy the violation(s). At present there are there what what drums BALTIMORE Post Office has fill August 4th what drum, to develope a Confungency plan so and to build a contament area.	e in † 198	the facelo	Ly.
5.	Continuation of the violation(s) or failure to take the corrective action described a legal sanctions against you, including the imposition of civil and/or criminal pend	bove m alties.	ay result in the D	epartment seeking
² eı	"I hereby acknowledge receipt of this Site Comptaint by my signature, which is no son issued to: Title: Title: Issued by: Assistant Secretary for Environmental Programs Phone: Phone:	/eL usi@	Inspector	*

HMH 4158



State of Marylano Department of Health and Mental Hygiene Office of Environmental Programs 201 West Preston Street, Baltimore, Maryland 21201

Report of Observations

Type of Inspection/Obser	
Facility Name:	US POSTAN SERICE
Remarks:	Vehicle Mointenance
	60 West Oliver street
	Balkinose, MO. 21201
	MODOWATE
	On August 4th 1986 U.S. Postal Services
Was not	ered to build a confairment area for the
handou	is waste and to develope a contamigency
- clan an	ed emissency procedurs.
	On the above date I met with me.
Peters 1	Leonard for a follow up inspection. The
Edmin	y was noted. The containment area
In the	hogundous waste is will. The containgen
Nan a	mal summanant procedures in development
	The facility must give a classroom
an site to	aming to the braility plansmort.
	maring for me foresty persons -
	<i>PA</i>
	e Retta Person Interviewed: 2008-
	e Ketto Person Interviewed: XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

Hazardous Waste Quantity Notification

U.S. Postal Service Value

Business Name
Superintendent, Vehicle Maintenance
60 W. Oliver Street
Business Address
Business Address

Business Address

Business Address

Business Address

M. D.D. 98 070 7483

Hazardous Waste Generated

0 - 100 kg/month

100 - 1000 kg/month

1000 kg/month or more

A. D. Redd Supt Veh Maint

Signature and Title



Official Business Penalty for Private Use \$300 FIRST-CLASS MAIL POSTAGE & FEES PAID EPA PERMIT NO. G-35

United States Environmental Protection Agency Washington DC 20460

JOHN A ARMSTEAD VA/WV SECTION (3HW31) US EPA REGIONIII 841 CHESTNUT ST. PHILADELPHIA, PA 19107

EPA Form 5180--11 (5-79)

. .

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY FACILITY INSPECTION PROGRAM

Environmental Science Center 701 Mapes Road Fort Meade, Maryland 20755-5350 (410) 305-2779

Enforcement Confidential, Attorney Client Privilege

Subject: Multi Media Compliance Inspection
U. S. Postal Service, Baltimore Vehicle Maintenance Facility

To: Samantha Fairchild, Director, OECEJ (3EC00)

From: Gerard Crutchley, OECEJ (3EC10)

On November 24, 2003, Gerard Crutchley and Jose Jimenez with EPA Region III's Office of Enforcement, Compliance and Environmental Justice (OECEJ) accompanied by a representative from the Maryland Department of the Environment (MDE) conducted a multi media compliance inspection at the U.S. Postal Service's Baltimore Vehicle Maintenance Facility located at 60 W. Oliver St. in Baltimore, Maryland. Following are the findings from the inspection:

- 1. At the time of the subject inspection wash water with some oil and anti freeze was observed flowing into a storm water drain in the parking lot behind the facility building. According to the MDE representative, the State of Maryland requires that any facility where vehicles are stored must apply for a general storm water discharge permit. The facility did have a storm water permit until February 2000 when they requested an exclusion from the permit requirements. Apparently the exclusion was granted but it was not known if the State was aware that the facility stored vehicles at their site. During the inspection, the MDE representative informed facility personnel that within fourteen days of the inspection they would need to obtain coverage under a General Industrial Permit and within thirty days develop a storm water pollution prevention plan.
- 2. The facility has a paint spray booth that they use for vehicle refinishing. The facility was issued an air permit which contains specific limitations for the amounts of volatile organic compounds (VOC) contained in paint/coating products used for vehicle refinishing. Based on a comparison of the permit limitations with the amounts of VOCs in the paint/coating products purchased by the facility, it appears that the facility exceeded the limitations in their permit.
- 3. The facility's paint spray booth is equipped with 40 exhaust filters and 8 intake filters.

 According to facility personnel, they change out the filters about every six months and the

dirty filters are disposed of as regular trash. The facility has never had the filters tested to determine if they could be categorized as hazardous waste.

VEHICLE MAINTENANCE FACILITY



December 6, 2004

Samantha P. Fairchild, Director
Office of Enforcement, Compliance and Environmental Justice
United States Environmental Protection Agency
Region III
1650 Arch Street
Philadelphia, PA 19103-2029

Dear Ms. Fairchild

I received the attached letter indicating that a Notice of Violation was issued for the U.S. Postal Service Baltimore Vehicle Maintenance Facility at 60 W Oliver Street, Baltimore MD. I have contacted DPRA Inc. and a representative will be here tomorrow, December 7, 2004 to obtain a sample of the paint booth filters. The representative, Jon Kallen, could not give me an exact date of completion, but indicated that it should be within the thirty days allowed in your letter.

As soon as the results are available I will send them to you.

Sincerely

Leonard C. Peters

Manager Vehicle Maintenance

U.S. Postal Service

Baltimore MD



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION III

1650 Arch Street Philadelphia, Pennsylvania 19103-2029

CERTIFIED MAIL RETURN RECEIPT REQUESTED

Leonard Peters, Manager United States Postal Service Baltimore Vehicle Maintenance Facility 60 W. Oliver Street Baltimore, Maryland 21201-5783

Re: Notice of Violation

Compliance Evaluation Inspection

November 24, 2003

Baltimore Vehicle Maintenance Facility

EPA ID No. MDD980707483

Dear Mr. Peters:

On November 24, 2003, the U.S. Environmental Protection Agency, Region III ("EPA") conducted a Compliance Evaluation Inspection ("CEI") under the Code of Maryland Annotated Regulations ("COMAR") and the Resource Conservation and Recovery Act ("RCRA"), as amended, 42 U.S.C. Sections 6901 et seq. This CEI was part of a multi-media inspection conducted at your facility. Based on the inspection, EPA has determined that the United States Postal Service - Baltimore Vehicle Maintenance Facility ("BVMF" or the "Facility") was in violation of regulations promulgated under the COMAR and RCRA. As a result of this finding, the Agency is issuing this **Notice of Violation (NOV)**. The specific violation is:

Docket No.: R3-05-NOV-RCRA-04

1. At the time of the November 24, 2003 inspection, the EPA inspectors observed the facility's paint spray booth equipped with an air circulation system that contains 40 exhaust filters and 8 intake filters. According to facility representatives, the spent air filters had never been analyzed for hazardous characteristics. The filters are changed about every six months, and are disposed as regular trash.

Under COMAR 26.13.03.02, a person who generates a solid waste, as defined in COMAR 26.13.02.02, shall determine if that waste is a hazardous waste using the following method: The person should first determine if the waste is excluded from regulation under COMAR 26.13.02.04 - .04-5. He shall then determine if the waste is listed as a hazardous waste in COMAR 26.13.02.15 - .19. If the waste is not listed as a hazardous waste in COMAR 26.13.02.15 - .19, he shall determine whether the waste is identified by either: (a) Testing the waste or (b) Applying knowledge of the hazard characteristic of the waste in light of the materials or the processes used.

Customer Service Hotline: 1-800-438-2474

BVMF failed to determine whether the spent air filters were hazardous waste, as required under COMAR 26.13.03.02.

A copy of the inspection report was sent to your office on February 10, 2004, but an extra copy of the report, documenting the findings of the EPA's inspectors, is enclosed for your information.

Within thirty (30) calendar days of the receipt of this NOV, please submit documentation of any measures the United States Postal Service - Baltimore Vehicle Maintenance Facility has taken or is taking to achieve compliance with the regulation noted above or provide an explanation of facts and circumstances that cause you to believe that EPA's determination of the alleged violation is in error. If the compliance measures identified are planned or are on-going, please provide a schedule for completing the compliance measures. Section 3008(a) of RCRA authorizes EPA to take an enforcement action whenever it is determined that any person has violated, or is in violation, of any requirement of RCRA as amended. Such an action could include a penalty of up to \$27,500 per day of violation. In addition, failure to achieve and maintain compliance with the regulation cited in this NOV may be treated as a repeated offense and may constitute a "knowing" violation of Federal law.

This NOV is not intended to address all past violations, nor does it preclude EPA from including any ongoing, including the ones cited in this letter, or past violations in any future enforcement action. The response to this NOV shall be addressed to:

José J. Jiménez U.S. Environmental Protection Agency - Region III Office of Enforcement, Compliance and Environmental Justice (3EC00) 1650 Arch Street Philadelphia, Pennsylvania 19103-2029

Samantha P. Fairchild, Director

Office of Enforcement, Compliance

and Environmental Justice

Enclosure

cc:

B. Dye (MDE) w/o enclosure

G. Crutchley (3EC10)w/o enclosure

J. Jiménez (3EC00)w/o enclosure

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION III

1650 Arch Street Philadelphia, Pennsylvania 19103-2029

SUBJECT: Notice of Violation

November 5, 2004

United States Postal Service

Baltimore Vehicle Maintenance Facility

FROM:

José J. Jiménez, Environmental Engineer

RCRA Compliance and Enforcement Branch (3EC00)

TO:

Samantha P. Fairchild, Director

Office of Enforcement, Compliance and Environmental Justice (3EC00)

I recommend that you sign the attached Notice of Violation which addresses a violation under the Code of Maryland Annotated Regulations ("COMAR"), and the Resource Conservation and Recovery Act ("RCRA"), by the United States Postal Service Baltimore Vehicle Maintenance Facility located in Baltimore, Maryland.

A. Respondent

United States Postal Service Baltimore Vehicle Maintenance Facility EPA ID No. MDD980707483

B. Type of Action

The recommended action is a Notice of Violation for a RCRA Subtitle C violation.

C. Summary of the Case

The United States Postal Service Baltimore Vehicle Maintenance Facility is a Conditionally Exempt Small Quantity Generator. The facility has not prior violations under the RCRA program. On November 24, 2003, the or Office visited the facility to conduct a multi- media inspection. Based on the inspection, EPA has determined that United States Postal Service Baltimore - Vehicle Maintenance Facility was in violation of regulations promulgated under the COMAR and RCRA.

At the time inspection, the EPA inspectors observed the facility's paint spray booth. The booth is equipped with an air circulation system that contains 40 exhaust filters and 8 intake filters. According to facility representatives, the spent air filters had never been analyzed for hazardous characteristics. The filters are changed about every six months, and are disposed of as regular trash.

Under state and federal requirements a generator of a solid waste shall determine if that waste is a hazardous waste

D. State or City Involvement

The State's enforcement contact was notified on October 28, on this coming enforcement action. On November 4, 2004, I spoke with Rick Johnson, from the Maryland Department of the Environment, to discuss this Notice.

E. Respondent's RCRA History

No violations over the last five years.

F. EPA Policy Impact

This case is consistent with EPA policy.

G. Public and Congressional Relations

No special or congressional concern is expected in response to this action.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION III

1650 Arch Street Philadelphia, Pennsylvania 19103-2029

CERTIFIED MAIL RETURN RECEIPT REQUESTED

Leonard Peters, Manager United States Postal Service Baltimore Vehicle Maintenance Facility 60 W. Oliver Street Baltimore, Maryland 21201-5783

Re: Notice of Violation

Compliance Evaluation Inspection

November 24, 2003

Baltimore Vehicle Maintenance Facility

EPA ID No. MDD980707483

Dear Mr. Peters:



Docket No.: R3-05-NOV-RCRA-04

On November 24, 2003, the U.S. Environmental Protection Agency, Region III ("EPA") conducted a Compliance Evaluation Inspection ("CEI") under the Code of Maryland Annotated Regulations ("COMAR") and the Resource Conservation and Recovery Act ("RCRA"), as amended, 42 U.S.C. Sections 6901 et seq. This CEI was part of a multi-media inspection conducted at your facility. Based on the inspection, EPA has determined that the United States Postal Service - Baltimore Vehicle Maintenance Facility ("BVMF" or the "Facility") was in violation of regulations promulgated under the COMAR and RCRA. As a result of this finding, the Agency is issuing this **Notice of Violation (NOV)**. The specific violation is:

1. At the time of the November 24, 2003 inspection, the EPA inspectors observed the facility's paint spray booth equipped with an air circulation system that contains 40 exhaust filters and 8 intake filters. According to facility representatives, the spent air filters had never been analyzed for hazardous characteristics. The filters are changed about every six months, and are disposed as regular trash.

Under COMAR 26.13.03.02, a person who generates a solid waste, as defined in COMAR 26.13.02.02, shall determine if that waste is a hazardous waste using the following method: The person should first determine if the waste is excluded from regulation under COMAR 26.13.02.04 - .04-5. He shall then determine if the waste is listed as a hazardous waste in COMAR 26.13.02.15 - .19. If the waste is not listed as a hazardous waste in COMAR 26.13.02.15 - .19, he shall determine whether the waste is identified by either: (a) Testing the waste or (b) Applying knowledge of the hazard characteristic of the waste in light of the materials or the processes used.

Customer Service Hotline: 1-800-438-2474

BVMF failed to determine whether the spent air filters were hazardous waste, as required under COMAR 26.13.03.02.

A copy of the inspection report was sent to your office on February 10, 2004, but an extra copy of the report, documenting the findings of the EPA's inspectors, is enclosed for your information.

Within thirty (30) calendar days of the receipt of this NOV, please submit documentation of any measures the United States Postal Service - Baltimore Vehicle Maintenance Facility has taken or is taking to achieve compliance with the regulation noted above or provide an explanation of facts and circumstances that cause you to believe that EPA's determination of the alleged violation is in error. If the compliance measures identified are planned or are on-going, please provide a schedule for completing the compliance measures. Section 3008(a) of RCRA authorizes EPA to take an enforcement action whenever it is determined that any person has violated, or is in violation, of any requirement of RCRA as amended. Such an action could include a penalty of up to \$27,500 per day of violation. In addition, failure to achieve and maintain compliance with the regulation cited in this NOV may be treated as a repeated offense and may constitute a "knowing" violation of Federal law.

This NOV is not intended to address all past violations, nor does it preclude EPA from including any ongoing, including the ones cited in this letter, or past violations in any future enforcement action. The response to this NOV shall be addressed to:

> José J. Jiménez U.S. Environmental Protection Agency - Region III Office of Enforcement, Compliance and Environmental Justice (3EC00) 1650 Arch Street Philadelphia, Pennsylvania 19103-2029

Samantha P. Fairchild, Director

Office of Enforcement, Compliance

and Environmental Justice

Enclosure

cc:

B. Dye (MDE) w/o enclosure

G. Crutchley (3EC10)w/o enclosure

J. Jiménez (3EC00)w/o enclosure